January Operations Report Forest View Acres

31.27

This report will include any and all work and projects during the month of January.

- Arapahoe plant floor cracking under the filter treatment system, and pumps. Suspect water that has pooled up and washed underneath the building for awhile. Called RTW for floor plan to look at plan to repair.
- The major cross connection at the surface water plant (SWP) was called into the State January 12th. The State was pleased that we reported it. The diagram and the plan from ASCG were faxed to them as well. Waiting for report back.
- The Dawson Well was tested January 8th, 9th, and 10th by AM West. I will send in the report as soon as it is completed.
- FVA had four water leaks/breaks within a week. One, a prv had a ¾ inch line was causing water to fill the prv vault. Water was pumped down, the prv bypass open, line fixed and the prv back in service within one hour.
- The second break was on Pike View and Sierra Vista where a connection cracked the 6 inch schedule 40 pvc. This was the third break in this area based on the repair clamps. Thirty people were without water for about 20 hours.
- The third break was on Oxbridge Rd. where a saddle clamp failed. This caused damage to a service line. About 48 people were out of water for about 14 hours. Valves were found in order to isolate only about 5 6 people without water. The water was back on for those 5-6 residents within 10 hours.
- The fourth break was about 6 days later. This was on 3815 Sierra Vista, where a glue joint failed. Water was off for only about one hour. This is the 5th break in this area according to the resident. Schedule 40 pvc is the line.
- Replacement clamps were ordered to replenish the stock.
- The chlorine analyzer has not been working. New prvs will be installed to allow the correct water flow to the new unit. Once this is completed, the plant will be able to run continually 7 days a week.
- Shipment of poly has arrived. The shipment should have been here by Christmas. The snow storms delayed the shipment.
- Maintenance schedules, distribution work, and plant maintenance schedules are being planned for the near future. This includes location of valves, valve markers, prv inspections, cs inspections, hydrant checks, ordering maintenance parts, filter control maintenance, pump line repair and installation at the SWP.

FOREST VIEW ACRES WATER DISTRICT PRODUCTION REPORT FOR 2007

Californs Cali
1,186,799
24.628 Service to the formal of the following service to the following
1,492,463 56,174.49 1,2,000 1,2,000 1,2,000 1,2,000 1,2,000 1,3,000